



Urine Specimen Collection

Straight Cath (mini-cath):

1. Clean urethral area and rinse.
2. Insert catheter into bladder.
3. Discard first 15ml.
4. Collect remainder of urine into a sterile screw-cap container.